

RiedonPowertron

Part Number Conversion

Current Riedon Part #	New Global Part #	Image
PF1121	USR 4-4020	
PF1121H	UNR 4-4020	
PF1122	USR 4-3425	
PF1122H	UNR 4-3425	
PF1140	FHR 2-8065	
PF1140-4	FHR 4-8065	
PF1141	FHR 2-80110	
PF1141-4	FHR 4-80110	
PF1142	FHR 2-80216	
PF1142-4	FHR 4-80216	
PF1143	FHR 2-80320	
PF1143-4	FHR 4-80320	
PF1144	FHR 2-80370	
PF1144-4	FHR 4-80370	
PF1220	USR 2-T220	
PF1220-4	USR 4-T220	
PF1220S	USS 2-T220	
PF1220S-4	USS 4-T220	
PF1221	USR 2-T221	
PF1227	FPR 2-T227	
PF1227-4	FPR 4-T227	
PF1227H	FNR 2-T227	
PF1227H-4	FNR 4-T227	
PF1261	NPR 2-T216	
PF1261-4	NPR 4-T216	
PF1262	NPP 2-T216	
PF2160	USR 2-0710	
PF2161	USR 2-1410	
PF2161-4	USR 4-1410	

Current Riedon Part #	New Global Part #	Image
PF2162	UPW 2-0808	
PF3101	FPR 2-2614	
PF3102	FPR 4-3316	
PF3103	FPR 2-1617	
PF3104	FHR 2-3025	
PF3105	FHR 4-3825	
PF3218	FPR 2-T218	
PF3220	FPR 2-T220	
PF3220-4	FPR 4-T220	
PF3220S-4	FPS 4-T220	
PF3221	FPR 2-T221	
PF3221-4	FPR 4-T221	
PF4163	USN 2-1410	
SSR	USS 2-0001 0003	
TF1218	KPR 2-T218	
TF1218H	KHR 2-T218	
TF1220	NPR 2-T220	
TF1220H	NHR 2-T220	
TF1220HS	NHS 2-T220	
TF1220HS-4	NHS 4-T220	
TF1220S-4	NPS 4-T220	
TF1221	NPR 2-T221	
TF1221H	NHR 2-T221	
TF1227	KPR 2-T227	
TF1227-4	KPR 4-T227	
TF1227H	KHR 2-T227	
TF1227H-4	KHR 4-T227	
TF1227N	KPN 2-T227	
TF1227NH	KHN 2-T227	